VERIFIED UTILITY INFORMATION

			۷۲۱۰	MILD OTH	II BNI OIM	MATION		M may
TEST HOLE #	SIZE &	TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
109	12"	W	14039071.270	2458870.762	416.37	5.80'	410.57	UTILITY QUALITY LEVEL "A"
· 110	6"	W	14039113.970	2458692.914	415.48	3.07	412.41	UTILITY QUALITY LEVEL "A"
110A	1,5"	W	14039114.710	2458692.420	415.51	3.20'	412.31	UTILITY QUALITY LEVEL "A"
111	10"	FM	14039608.580	2457878.964	397.60	1.94	395.66'	UTILITY QUALITY LEVEL "A"
111A	10"	FM	14039608.580	2457878.964	397.60'	3.01	394.59'	UTILITY QUALITY LEVEL "A"
112	16"	FM	14044181.945	2451425.631	403.80	2.23'	406.03'	UTILITY QUALITY LEVEL "A"
113	24"	FM	14044195,464	2451426.136	SEE NOTE	SEE NOTE	405.56'	SEE NOTE
114	24"	FM	14044740.055	2451511.310	398.17'	3.56'	401.73	UTILITY QUALITY LEVEL "A"
115	16"	FM	14044737.878	2451513.982	SEE NOTE	SEE NOTE	402.93'	see note
116	16"	FM	14045312.801	2451601.700	SEE NOTE	SEE NOTE	403.44'	see note
117	24"	FM	14045315.870	2451595.033	399.70'	1.72	401.42*	UTILITY QUALITY LEVEL "A"
118	SEE	NOTE	14045561.693	2452496.355	SEE NOTE	SEE NOTE	414.82'	see note
119	SEE	NOTE	14045552.786	2452466.195	SEE NOTE	SEE NOTE	414.43'	see note
		·						
-								
		,						- Calculation of the Control of the

VERIFIED UTILITY INFORMATION

EST DLE #	SIZE	<^~ &c	TYPE	NORTHING	EASTING	EXISTING TOP ELEVATION	EXISTING CUT	REFERENCE ELEVATION	COMMENTS
- #						101 222			
	•	W-1-4		A CONTRACTOR OF THE PARTY OF TH					
			·····					·	
						ļ			

	.,								
i									
			- Mrs VV					······································	
									and the state of t
	•								
				and the rest of th				77-777-17-14-16-16-16-16-16-16-16-16-16-16-16-16-16-	
							,		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							······································	
					'				•
				:					
			and the section of th						
	and the second second second								and the state of t

		******			 			T-010) ~	- The state of the
				.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
				**					
				*					
				-					

ABBREVIATIONS NOTES FM = FORCE MAIN W = WATER MAIN TEST HOLE #111 & #111A - FOUND (2) 10 PIPES ONE STACKED ON TOP OF THE OTHER. REF.

TEST HOLE #113, #115 & #116 - PIPE WAS EXPOSED ABOVE GROUND.

POINT WAS PLACED ON CENTER OF BOTH PIPES.

TEST HOLE *118 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE ONLY ABLE TO PROBE TO A DEPTH OF 15.24' AT WHICH POINT WE FELT SOMETHING SOLID BUT COULD NOT VERIFY IF IT WAS

TEST HOLE #119 - DUE TO LARGE AMOUNT OF DEBRIS WE WERE NOT ABLE TO EXCAVATE PAST 5'. NO UTILITY WAS FOUND.

ALL INFORMATION SHOWN WAS OBTAINED FROM A LOCATION SURVEY.



SCALE:

REV1	SIONS
NAME	DATE

SUE INVESTIGATION OF UNDERGROUND UTILITIES VERIFIED UTILITY MATRIX

MISSISSIPPI RIVER BRIDGE PROJECT CONTRACT NO: D-98-061-08

S	PROJECT NO: IL09500610
	DATE: 7/15/10
	DRAWN BY: KLC
	CHECKED BY: EG
	SREET NO:
	1 OF 1

DESIGNED EG REVISED FILE NAME = REVISEO SFILELS CHECKED JB REVISED PLOT DATE = #DATE# DATE 9/15/09 REVISEO

STATE OF ILLINOIS **DEPARTMENT OF TRANSPORTATION**

		DUICS	
Mississippi Rive	r Bridge	Project	F.A. RTE.
SHEET NO.	STA.	TO STA.	550 BD40 0

				205.800.100				
7	SE	CTION		COUNTY	TO: SHE	TOTAL SHI SHEETS N		
1				St. Clofr	- 3!	53	158	
				PTB	NO. I	47-0	38	
RGAD	015%, NO.	ILLINOIS	Job 8	80-98-08	1-08			